

⚠️ WARNING

1. Always Maintain shooter's Minimum Safe Distance of:

30 feet for handguns



← **Minimum 30 Feet** →



50 yards for rimfire rifles



← **Minimum 50 Yards** →



150 yards for centerfire rifles



← **Minimum 150 Yards** →



Shooter shall not get closer than these distances to any Lewis Targets. All others should stay behind the line of fire.

2. Always wear approved safety glasses & ear protection when shooting or observing shooting at any Lewis Target.
3. Never fire a gun under the influence of alcohol or drugs.
4. Do not use jacketed ammunition, as this increases the likelihood of bullet ricochet.
5. All shooters must be trained & qualified in the proper and safe use of firearms.
6. Minors shooting at targets must do so under proper and qualified adult supervision.
7. Always inspect the targets before & after use for proper and safe operation. Do not use a target if any damage or improper operation is found.



Lewis Manufacturing Co.

3601 S. Byers ♦ Oklahoma City, OK 73129

888-398-4719

RangeMasterRowdy.com